



OIL PRESSURE RELIEF VALVE

Subject: broken oil pressure relief valve

Model: Breva 750

Problem:

oil pressure relief valve breaks in the area where the oil outlet holes are.

Solution:

change the oil pressure relief valve with the component used for the Breva 750 engine.