

## GEAR CHANGE PAWL SPRING

**Subject:** broken gear change pawl spring

Model: V11

*Problem:*

broken gear change pawl spring

*Solution:*

In case of breakage of the pawl spring (**A**) in vehicles with frame numbers before **KT111435 - KS112350**, the pawl (**B**) should be changed (when asking for the spare part, you automatically receive the pawl updated version).

The change consists in the reduction of the diameter on which the spring rests from 16 mm to **15 mm**.

