
EXHAUST SILENCERS

Subject: exhaust silencers

Model: Breva 750

Problem:

The exhaust silencers come off due to the inadequate length of the exhaust pipes.

Solution:

For the new bikes, the exhaust pipe length has been changed.

For the bikes already manufactured, the problem can be solved by cutting slots on the silencer brackets (A).

