



THROTTLE POSITION DATA MISSING

Subject: Throttle position data missing

Model: Breva 750

Problem:

the engine does not work correctly and tends to stop. The parameter "**Correct throttle pos**" read with Axone indicates **2.3 °** (normally, it should read between **2.7°** and **3.5°**).

Solution:

reset the throttle with Axone.

Adjust the cylinder synchronization and idle speed.